

Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Front Entrance, September 23, 2017



Front Entrance, November 17, 2017



Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Fire Damaged Roof & Fascia, September 23, 2017



Repaired Roof & Fascia, November 14, 2017



Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Front Foyer, September 23, 2017



Front Foyer, November 21, 2017



Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Family Room, September 23, 2017



Family Room, November 17, 2017



Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Family Room, September 23, 2017



Family Room, November 17, 2017




Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Fire Damaged Hallway, September 23, 2017



Fire Damaged Hallway, November 18, 2017



Mostly Undamaged Dining Room, November 12, 2017



Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Kitchen, November 5, 2017



Kitchen, November 21, 2017



Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Damaged Bedroom, November 5, 2017



Damaged Bedroom, November 17, 2017



Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Child's Bedroom Where Fire Started, September 23, 2017



Child's Bedroom Where Fire Started, November 17, 2017



Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Damaged Bedroom, November 5, 2017



Least Damaged Bedroom, November 18, 2017



Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Damaged Master Bedroom, November 5, 2017



Damaged Master Bedroom, November 21, 2017



Tiffany Wilson Lane
2340 Carlton Avenue, Boothwyn, PA 19061

Laundry Room, November 5, 2017



Laundry Room, November 21, 2017

